

Ag

Cu

Ni

Sn

## Handling & Storage Instruction

### Handling

Please handle and store our Shieldex® products with care.

For working with our metallized material, please use white lint-free cotton gloves to avoid spots or fingerprints, caused by wet or oily hands, starting with the goods receipt until the end of the production process.

Furthermore, we recommend cleaning the working area before processing our Shieldex® products. Moisture and grease can cause irreversible stains on the surface of our products.

### Storage

Please note the following for the storage of our products:

- Store in original packing
- Store at regularly room temperature (20 °C ± 2 °C and 50 % ± 10 % humidity)
- Do not store into directly insolation
- Do not store into atmosphere with acid and / or alkalis (also the free sulfur in the air can damage the silver surface)

Claims caused by wrong handling/storing will not be accepted by Statex Produktions- und Vertriebs GmbH.